

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 2a




FIG. 2b

METHOD FOR DETECTION OF DEFECTS IN ANISOTROPIC MATERIALS

Peter William Lorraine et al.

ATTORNEY DOCKET NO. RD25422-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




Fig. 3

METHOD FOR DETECTION OF DEFECTS IN ANISOTROPIC MATERIALS

Peter William Lorraine et al.

ATTORNEY DOCKET NO. RD25422-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




Fig. 4

METHOD FOR DETECTION OF DEFECTS IN ANISOTROPIC MATERIALS

Peter William Lorraine et al.

ATTORNEY DOCKET NO. RD25422-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




Fig. 5

METHOD FOR DETECTION OF DEFECTS IN ANISOTROPIC MATERIALS

Peter William Lorraine et al.

ATTORNEY DOCKET NO. RD25422-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




Fig. 6

METHOD FOR DETECTION OF DEFECTS IN ANISOTROPIC MATERIALS

Peter William Lorraine et al.

ATTORNEY DOCKET NO. RD25422-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11